



PT. CITRA TRININDO INDONESIA

Contractor, Mechanical, Electrical, Fabrication, Chemical General Trading

Jl. Raya Cikarang Cibarusah No. 12 Telaga Pasir Raya, Bekasi, Jawa Barat 17330

Telp & Fax. (021) 29253566 E-mail : info.ptcti18@gmail.com

www.perlengkapanindustri.com | www.Tokokimia.org | www.Tabungpemadamapi.co.id

22 September 2022

MATERIAL SAFETY DATA SHEET MOULD CLEANER

1) SUBSTANCE AND COMPANY IDENTIFICATION

Product Name : Mould Cleaner
Chemical Family : Mould Cleaner
Manufacture : PT. Citra Trinindo Indonesia
Address : Jl. Raya Cikarang Cibarusah No. 12 Perum. Telaga Pasir Sari, Sukasari, Serang Baru, Bekasi, Jawa Barat
Telp : (021) 8928 4199

2) COMPOSITION / INFORMATION ON HAZARDOUS INGREDIENTS

The precise composition of this mixture is proprietary information. A complete disclosure will be provided to a physician or nurse in the event of a medical emergency.

<u>Component</u> =====	<u>CAS</u>	<u>Composition</u> =====
- Dichlorofluoroethane	1717-00-6	60 - 70 %
- Isopropil Alkohol	67-63-0	10 - 15 %
- Propane /Buthane	74-98-6	25 - 30 %

Eyes : This product causes eye irritation upon contact. Avoid contact with eyes.
Skin : This product may cause skin irritation upon long time direct contact. Prolonged or repeated contact may result in dermatitis, oil acne, folliculate, edema. Contact dermatitis is characterized by dryness, chapping and reddening.
Inhalation : Excessive inhalation may cause local irritation, dizziness and nausea.
Ingestion : Ingestion of this product may cause gastrointestinal irritation, nausea, vomiting and diarrhea.

4) FIRST AID MEASURES

Thoroughly flush affected area with large quantities of water.
Remove and wash all contaminated clothing before use.

Inhalation: If overexposure occurs, remove victim to fresh air immediately. If breathing has stopped, apply artificial respiration and administer oxygen if necessary. Seek medical attention immediately.

Eye Contact: Flush eyes with large amounts of water for at least 15 minutes while holding eyelids open. Seek medical attention immediately.



PT. CITRA TRININDO INDONESIA

Contractor, Mechanical, Electrical, Fabrication, Chemical General Trading

Jl. Raya Cikarang Cibarusah No. 12 Telaga Pasir Raya, Bekasi, Jawa Barat 17330

Telp & Fax. (021) 29253566 E-mail : info.ptcti18@gmail.com

www.perengkapanindustri.com | www.Tokokimia.org | www.Tabungpemadamapi.co.id

22 September 2022

Skin Contact: Flush with water while removing contaminated clothing and shoes. Wash exposed portions of the skin with soap and water. Do not use clothing and shoes until thoroughly cleaned and decontaminated. Discard all leather articles soaked with this product.

Ingestion: Do not induce vomiting. Give two glasses of water if the person is conscious. Do not give any liquid if the person is unconscious or very drowsy. Keep the person warm and quiet. Seek medical attention immediately.

5) FIRE FIGHTING MEASURES

This product does not pose an unusual fire fighting problem. It will burn if involved in a fire.

Use foam, dry chemicals, CO₂, sand/earth to extinguish fire. Water may be used to cool exposed container. The product may float on water and reignite.

Do not enter confined fire space without full bunker gear (helmet with face shield, bunker coats, gloves and rubber boots), including a positive-pressure NIOSH approved self-contained breathing apparatus.

6) MEASURES FOR ACCIDENTAL RELEASES

Put on protective clothing before starting the clean up. Contain spill and stop the leak at the source if safe to do so and notify the appropriate authorities of the spill. Material may burn although not readily ignitable. Use cautious judgment when cleaning up large spills. Soak up small spills with a non-combustible absorbent. Large spills can be removed by a vacuum truck or pump to storage vessels. Flush area with large amounts of water to in-house treatment system to remove trace residues. Do not directly flush to the sewer or surface waters. Dispose of the material in accordance with federal, state and local area regulations.

7) HANDLING AND STORAGE

HANDLING:

Use good engineering practices to establish good ventilation. For normal use, wear rubber gloves, coveralls, boots and gloves. If a mist of this material is present or the ventilation is poor then use mist type respirator and a local exhaust is required for the mist.

Do not eat or drink while handling the material. Wash hands thoroughly with soap before eating.

STORAGE:

Do not transfer the material to unmarked containers. Store in closed containers away from extreme heat, sparks, open flame, or oxidizing materials. Fire extinguishers should be kept available at all times.



PT. CITRA TRININDO INDONESIA

Contractor, Mechanical, Electrical, Fabrication, Chemical General Trading

JL. Raya Cikarang Cibusah No. 12 Telaga Pasir Raya, Bekasi, Jawa Barat 17330

Telp & Fax. (021) 29253566 E-mail : info.ptcti18@gmail.com

www.perengkapanindustri.com | www.Tokokimia.org | www.Tabungpemadamapi.co.id

22 September 2022

8) EXPOSURE CONTROL AND PERSONAL PROTECTION EQUIPMENT

Use oil resistant rubber gloves, boots, coveralls and goggles under normal use. Local exhaust, ventilation, mist type respirator and face shield are required under mist conditions.

9) PHYSICAL & CHEMICAL PROPERTIES

Appearance : clear
Boiling Point : > 100°C
Odour : Characteristic
Melting point : NA
Specific Gravity : 0,668 gr/cm³
Water Solubility : Not soluble
Vapor density (Air=1) ; NA

10) STABILITY & REACTIVITY

Stable under normal conditions and use.
Heat, flame or addition of strong oxidizing materials such as chromic acid, hydrogen peroxide and bromine may cause decomposition.
Decomposition products may include CO, CO₂, SO₂ and other unidentified organic compounds.

11) TOXICOLOGICAL DATA/INFORMATION

May cause skin and eye irritation.

12) ECOLOGICAL INFORMATION

No specific data is available.

13) DISPOSAL CONSIDERATION

Rinse containers well with water before disposal. Preferably re-cycle container, otherwise send to an authorized landfill or similar.

14) TRANSPORT INFORMATION

This substance is not classified as dangerous goods for Land Transport in New Zealand according to NZS5433: 2012 UN1791 – (Hypochlorite solutions) with not more than 5% available chlorine is not subject to the provisions of the Land Transport Standard NZS5433:2012.



PT. CITRA TRININDO INDONESIA

Contractor, Mechanical, Electrical, Fabrication, Chemical General Trading

JL. Raya Cikarang Cibarusah No. 12 Telaga Pasir Raya, Bekasi, Jawa Barat 17330

Telp & Fax. (021) 29253566 E-mail : info.ptcti18@gmail.com

www.perengkapanindustri.com | www.Tokokimia.org | www.Tabungpemadamapi.co.id

22 September 2022

Sea Transport

UN 1791 Hypochlorite solution (less than 5% available chlorine) Class 8 PG III Marine Pollutant;

No

Air Transport

UN 1791 Hypochlorite solution (less than 5% available chlorine) Class 8 PG III

15) REGULATORY INFORMATION

EPA Approval Code:

Cleaning Products (subsidiary hazard) – HSR002530

HSNO Controls:

Trigger quantities for this substance:

	Trigger Quantity
Approved Handler	Not required
Location Certificate	Not required
Tracking Trigger Quantities	Not applicable
Signage Trigger Quantities	1000L (9.1B)
Emergency Response Plan trigger Quantities	1000L (9.1B)

16) OTHER INFORMATION

SDS Version Number: 1.2

SDS Effective Date: 11 August 2016

SDS Review Date: 11 August 2021

SDS Regulation: The content and format of this SDS is in accordance with HSNO Approved Code of Practice (No. HSNO COP 8-1 09-06): Preparation of Safety Data Sheets.

Disclaimer:

This document is compiled based on current knowledge as provided by 30 Seconds Ltd or information obtained from third party sources relating to safety and handling precautions for this product. SafeTech Consulting Ltd has taken all due care to include accurate and up-to-date information in this document and does not provide any warranty as to accuracy or completeness. The information herein is given in good faith, but no warranty, express or implied is made.